

Super Stock Chaos

- Any 1980 and newer 2-wheel drive passenger car, mini-van, mini-truck, mid-size SUV
- All vehicles must be stripped of all plastic, glass, headlights, taillights, and anything else that could fall off onto the track during the show.
- All vehicles must remain stock, ABSOLUTELY NO WELDING ANYWHERE.
- Bumpers must remain stock, do not alter bumper in anyway. Factory bumper shocks must remain in the factory location. You may remove rear bumpers and shocks. There is no welding to be done on bumpers.
- Batteries may be left in stock location and spray foam may be added around battery. You may also move the battery to the passenger floor seat. Please make sure the battery is secure.
- If the factory gas tank is in the front of the axle you may leave it there. If it's behind the axle, you must move it to the rear seat area. Factory tanks may be moved inside but completely secured. Aftermarket tanks may be allowed.
- All doors may be wired or chained in 6 places per seam.
- Trunks, hoods, tailgates all may be wired or chained in 6 places total. Sheet metal to sheet metal only. Nothing to frame or bumpers. If you remove the trunk or tailgate you lose that wire or chain.
- A rear seat bar may be added. It may be welded to post. This is only to stop sides from coming in, not to help any other part of the vehicle.
- Drivers door only may have a plate welded to the outside or inside. This is for the driver safety.
- DOT tires only. Stock wheels only. All wheel weights must be removed. Only tubes and air are permitted inside of the tires.
- Cars must keep OE ignition switch and start with that key only not straight wiring.
- No aftermarket wiring harness

These rules are cut and dry, you should not have to call and ask many questions on this class. If it does not say it in the rules, that means don't do it.

Claiborne County Fair